

2010 GULF OF MEXICO OIL SPILL

2010 GULF OF MEXICO

Live: Spill Cam

• <u>'Top Kill' graphic</u>

Track oil spill

NOAA trajectory

How it happened

 Latest photos Latest video 🗇 How to help

> 'Save the Gulf of Mexico' on Facebook

Spill public blog

LATEST HEADLINES Gov. Bobby Jindal to attend barrier island berm meeting

 U.S. Attorney General Eric Holder to tour Gulf

• Oil spill video: BP's Bob

Dudley explains next

everywhere, but there

BP alters plan for next

attempt to contain oil

BP's Deepwater Horizon Response Joint

Information Center has

offered the following

numbers for residents: · To report oiled wildlife,

call 866.557.1401

To report oiled shoreline

or request volunteer

information, call

866.448.5816

GO ►

attempt to CNN

Oil spill angst is

are healthy and unhealthy ways of dealing with it

from Gulf spill

Browse by month:

Select a date

HOW TO HELP

oil spill

Post updates on our Oil

Write your post now

OIL SPILL

Latest news, photos, videos from the BP Deepwater Horizon drilling disaster

Breaking News »

Oil spill hearings: Rig had no power to fight fire after engines oversped with The Times-Picanune

By David Hammer, The Times-Picayune May 29, 2010, 9:14AM

This is an update from the joint hearings of the U.S. Coast Guard and Minerals Management Service held in Kenner on Saturday into the explosion and fire aboard the Deepwater Horizon oil rig on April 20, which killed 11 workers and created the Gulf of Mexico oil spill currently fouling Louisiana's coast.



Chris Granger / The Times-Picayune

Members of the Deepwater Horizon Joint Investigation team, from left, are: Lt. Robert Butts, USCG; Ross Wheatley, USCG; Capt. Hung Nguyen, USCG; David Dykes, MMS; Jason Mathews, MMS; and John McCarroll, MMS.

Testimony of motorman Paul Meinhart III

During the explosions April 20 on the Deepwater Horizon, the rig's diesel engines revved up and tripped an automatic power shut-off as gas seeped through ducts into the engine room, according to testimony Saturday in investigative hearings.

Motorman Paul Meinhart III testified that emergency generators didn't work after the first explosions rang out, and his subsequent attempts to manually start a backup electrical generator were also unsuccessful.

On Thursday, the rig's chief mate, David Young, testified that with no power, the rig's fire pumps didn't work and attempts to fight the fire were abandoned.

But given the enormity of the explosions from unexpected kicks of gas from the well below, Meinhart was skeptical that any power would have helped fight the fires.

"Due to the fact half the vessel was on fire at the time," he said.

Steve Gordon, a lawyer questioning Meinhart interrupted and continued the thought: "One more fire wouldn't have mattered, right?"

IN OIL SPILL VIDEO



Oil spill video: Reporters give latest 'Top Kill' news

MORE OIL SPILL VIDEOS »





OIL SPILL PHOTOS








MORE OIL SPILL PHOTOS »


INFOGRAPHICS FROM THE TIMES-PICAYUNE

Graphic shows how



Help Aid Wildlife Rescue

Register to volunteer







Lakeview Regional Medical Center www.lakeviewregional.com I-866-4-LAKEVIEW For job opportunities please visit, www.lakeviewregional.com

detection to know that gas was seeping all the way into the engine room? I think we are in our third or fourth generation of detection devices, and I can't fathom a project of this magnitude didn't have warning systems that would have alerted when the smallest amount of gas hit the surface. None of this is

Inappropriate comment? Alert us.

Reply to this comment | Post a new comment

The testimony being given, while rather guarded, appears to not want to

animated graphic

Track the Gulf of Mexico oil spill movement in

How the Gulf of Mexico oil spill happened: a graphic presentation

leaking oil well could be



Story roundup of the Gulf of Mexico oil rig explosion and spill

plugged by 'top kill' method

Nore Jobs Search All Jobs Post Your JOB now	 incriminate BP. thou they are the 'customer' and they called all the shots, Transocean, Dril-Quip, Halliburton and others all seem to indicate something was not right on the rig floor, yet no one will come out and say it. This wasnt some fluke accident, warning signs were ignored, mud was removed, and the "shears" according to one guy are there 'just in case'. Worse yet, MMS doesnt seem to have a clue as to what should or shouldnt be normal operating procedures, based on the questions they are asking. 	2
CONTESTS & EVENTS	Inappropriate comment? Alert us	5.
Get your news delivered for FREE!	Reply to this comment Post a new comment	
 Shop The Times Picayune Store Check out our contests! 	We've upgraded our community features on NOLA.com Learn more! »	
ADVERTISEMENT		
من Advance	Site Search Search Local Business Listings	Site Map Advertise Contact us
Advance [®] Internet	Site Search Search Local Business Listings Search by keyword, town name, Web ID and more	Site Map Advertise Contact us Make us your home page
W Internet		Make us your home page Make us your home page Make us your home page State Classifieds Shopping Place an Ad Subscribe to our content (RSS) News alerts
 Home News Weat Your Photos Your Videos 	Search by keyword, town name, Web ID and more ther Sports Entertainment Interact Living Jobs Autos Real Es Post a Job Post a free classified ad US & World News	Make us your home page tate Classifieds Shopping Place an Ad Subscribe to our content (RSS)

The Times-Picagune today and get incredible savings off home delivery! Subscribe Now!

© 2009 New Orleans Net LLC. All Rights Reserved (About Us). Use of this site constitutes acceptance of our User Agreement. Please read our Privacy Policy. Community Rules apply to all content you upload or otherwise submit to this site. Contact interactivity management.